

Certificate No: n1110577-ygv DNV GL Id No: G113647 Date of issue: 2018-01-28

# SAFETY MANAGEMENT CERTIFICATE

Issued under the provisions of the INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974, as amended under the authority of the Government of

### THE REPUBLIC OF THE MARSHALL ISLANDS

by **DNV GL** 

CALIDRIS
4621
MAJURO
Other cargo ship

Gross Tonnage: **35878**IMO Number: **9445899** 

IMO Number: 944!

Particulars of Company <sup>2</sup>

Company Name: Leonhardt & Blumberg Shipmanagement GmbH &

Co. KG

Company Address: Neumühlen 13 22763 Hamburg

GERMANY

Company Identification Number: 5979428

### This is to certify:

**Particulars of Ship** 

that the safety management system of the ship has been audited and that it complies with the requirements of the International Management Code for the Safe Operation of Ships and for Pollution Prevention (ISM Code), following verification that the Document of Compliance for the Company is applicable to this type of ship.

This Safety Management Certificate is valid until **2023-01-28**, subject to periodical verification and the validity of the Document of Compliance remaining valid.

Completion date of audit on which this Certificate is based: 2018-01-28

Issued at Busan, Republic of Korea on 2018-01-28



Revision: 2017-09

#### for **DNV GL**

This document is signed electronically in accordance with IMO FAL.5/Circ.39/Rev.2. Validation and authentication can be obtained from trust.dnvgl.com by using the Unique Tracking Number (UTN): n1110577-ygv and ID: G113647

Jin, Kwan Yong Surveyor

www.dnvgl.com

Page 1 of 3

See paragraph 1.1.2 of the ISM Code.

Form code: ISMV 101



UTN: n1110577-ygv © DNV GL 2014. DNV GL and the Horizon Graphic are trademarks of DNV GL AS.

Insert the standard IMO ship type.

Certificate No: **n1110577-ygv** Date of issue: **2018-01-28** 

Surveyor, DNV GL

## **Endorsement for periodical verification** THIS IS TO CERTIFY: that at the periodical verification in accordance with regulation IX/6.1 of the Convention and paragraph 13.8 of the ISM Code, the safety management system was found to comply with the requirements of the (to be completed between the second and third anniversary date) Place: Date: Signature: Surveyor, DNV GL Additional verification (if required) Additional verification\*: Place: Date: Signature: Surveyor, DNV GL Stamp Place: Date: Additional verification\*: Signature: Surveyor, DNV GL Stamp Place: \_\_\_\_\_ Date: \_\_\_\_ Additional verification\*: Surveyor, DNV GL Stamp If applicable. Reference is made to the relevant provisions of section 4.3 "Initial Verification" of the Revised Guidelines on Implementation of the International Safety Management (ISM) Code by Administrations adopted by the Organization by resolution Endorsement where the renewal verification has been completed and part B 13.13 of the ISM Code applies The ship complies with the relevant provisions of part B of the ISM Code, and the Certificate should, in accordance with part B 13.13 of the ISM Code, be accepted as valid until Place: Date: Signature:

Form code: ISMV 101 Revision: 2017-09 www.dnvgl.com Page 2 of 3

Certificate No: **n1110577-ygv** Date of issue: **2018-01-28** 

Endorsement to extend the validity of the Certificate until reaching the port of verification where part B 13.12 of the ISM code applies or for a period of grace where part B 13.14 of the ISM code applies

grace where part B 13.14 of the ISM code	
This Certificate should, in accordance with part B 13.12 o be accepted as valid until	r part B 13.14 of the ISM Code,
Place:	Date:
	Signature:
Stamp	Surveyor, DNV GL

Form code: ISMV 101 Revision: 2017-09 www.dnvgl.com Page 3 of 3